

ABSTRACT

A shaving aid for a razor is configured as a shaving aid strip with an indicator in the form of a geometrical pattern on the strip to indicate a change in the amount of shaving aid material in the strip. The disappearance of the geometrical pattern, which occurs as a result of shaving with the razor, is an indication of a change in shaving aid material in the strip and of the need to change the strip.